

County: 02 - Allegheny; Municipality: 02909 - Elizabeth Twp; Region: All; Operator: All; Unconventional Only: Yes  
Resolved Violations Only: No; Inspections With Violations Only: No; Inspection Category: All

Inspections from 8/1/2018 to 5/23/2019

Operator: HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC - Inspections: 53; Inspections With Violations: 2; Violations: 5; Enforcements: 1; Wells Inspected: 12

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2774193	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	09/12/2018	Routine/Complete Inspection	003-22466	APOLLO B 3M	Yes	820926 - APOLLO B WELL PAD ESCGP ESX16-003-0009	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	STEINGRABE, SAMUEL	SAIR	No Violations Noted	Site under construction well not drilled.

No Violations

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2774197	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	09/12/2018	Routine/Complete Inspection	003-22467	APOLLO B 5M	Yes	820926 - APOLLO B WELL PAD ESCGP ESX16-003-0009	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	STEINGRABE, SAMUEL	SAIR	No Violations Noted	Site under construction well not drilled.

No Violations

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2774201	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	09/12/2018	Routine/Complete Inspection	003-22468	APOLLO B 1M	Yes	820926 - APOLLO B WELL PAD ESCGP ESX16-003-0009	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	STEINGRABE, SAMUEL	SAIR	No Violations Noted	Site under construction well not drilled.

No Violations

DEP OFFICE OF OIL AND GAS MANAGEMENT

COMPLIANCE REPORT

5/23/2019 3:26:21 PM

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2774207	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	09/12/2018	Routine/Complete Inspection	003-22492	APOLLO B 1G	Yes	820926 - APOLLO B WELL PAD ESCGP ESX16-003-0009	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	STEINGRABE, SAMUEL	SAIR	No Violations Noted	Site under construction well not drilled.

No Violations

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2774215	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	09/12/2018	Routine/Complete Inspection	003-22493	APOLLO B 3G	Yes	820926 - APOLLO B WELL PAD ESCGP ESX16-003-0009	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	STEINGRABE, SAMUEL	SAIR	No Violations Noted	Site under construction well not drilled.

No Violations

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2774219	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	09/12/2018	Routine/Complete Inspection	003-22523	APOLLO B 1U	Yes	820926 - APOLLO B WELL PAD ESCGP ESX16-003-0009	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	STEINGRABE, SAMUEL	SAIR	No Violations Noted	Site under construction well not drilled.

No Violations

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2774222	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	09/12/2018	Routine/Complete Inspection	003-22524	APOLLO B 3U	Yes	820926 - APOLLO B WELL PAD ESCGP ESX16-003-0009	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	STEINGRABE, SAMUEL	SAIR	No Violations Noted	Site under construction well not drilled.

No Violations

DEP OFFICE OF OIL AND GAS MANAGEMENT  
COMPLIANCE REPORT

5/23/2019 3:26:21 PM

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2777284	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	09/20/2018	Routine/Complete Inspection	003-22466	APOLLO B 3M	Yes	820926 - APOLLO B WELL PAD ESCGP ESX16-003-0009	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	STEINGRABE, SAMUEL	SAIR	No Violations Noted	Well site under construction. Well not drilled.

No Violations

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2777286	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	09/20/2018	Routine/Complete Inspection	003-22467	APOLLO B 5M	Yes	820926 - APOLLO B WELL PAD ESCGP ESX16-003-0009	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	STEINGRABE, SAMUEL	SAIR	No Violations Noted	Well site under construction. Well not drilled.

No Violations

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2777288	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	09/20/2018	Routine/Complete Inspection	003-22468	APOLLO B 1M	Yes	820926 - APOLLO B WELL PAD ESCGP ESX16-003-0009	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	STEINGRABE, SAMUEL	SAIR	No Violations Noted	Well site under construction. Well not drilled.

No Violations

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2777290	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	09/20/2018	Routine/Complete Inspection	003-22492	APOLLO B 1G	Yes	820926 - APOLLO B WELL PAD ESCGP ESX16-003-0009	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	STEINGRABE, SAMUEL	SAIR	No Violations Noted	Well site under construction. Well not drilled.

No Violations

DEP OFFICE OF OIL AND GAS MANAGEMENT  
COMPLIANCE REPORT

5/23/2019 3:26:21 PM

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2777292	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	09/20/2018	Routine/Complete Inspection	003-22493	APOLLO B 3G	Yes	820926 - APOLLO B WELL PAD ESCGP ESX16-003-0009	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	STEINGRABE, SAMUEL	SAIR	No Violations Noted	Well site under construction. Well not drilled.

No Violations

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2777294	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	09/20/2018	Routine/Complete Inspection	003-22523	APOLLO B 1U	Yes	820926 - APOLLO B WELL PAD ESCGP ESX16-003-0009	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	STEINGRABE, SAMUEL	SAIR	No Violations Noted	Well site under construction. Well not drilled.

No Violations

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2777296	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	09/20/2018	Routine/Complete Inspection	003-22524	APOLLO B 3U	Yes	820926 - APOLLO B WELL PAD ESCGP ESX16-003-0009	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	STEINGRABE, SAMUEL	SAIR	No Violations Noted	Well site under construction. Well not drilled.

No Violations

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2809171	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	11/27/2018	Routine/Complete Inspection	003-22534	PLUTUS 3G	Yes	827093 - PLUTUS WELL PAD & CETO TANK PAD ESCGP ESX17-003-0010	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	STEINGRABE, SAMUEL	SAIR	No Violations Noted	Site Inspection in response to an objection received by the Department on



**DEP OFFICE OF OIL AND GAS MANAGEMENT  
COMPLIANCE REPORT**

11/15/2018. The objection indicates that a landowner is concerned about the proximity of the earth disturbance to Trib. 37515 to Youghiogheny River. At the time of inspection, no earth disturbance was being conducted. According to the E&S plan map, included as part of ESCGP, ESX17-003 0010, the Trib is approximately 75' from the approved Limit of Disturbance. PADEP Water Quality Specialist Steingrabe was accompanied by PADEP Water Pollution Biologist Michael Stephen and PADEP Aquatic Biologist Dr. Will Brogan. The Department photographed the stream condition and verified the locations of two unnamed tributaries. The unnamed tributaries are located near the north side of the proposed well pad. The Department photographed the existing wetland and the watering trough upgradient from the wetland. The Biologist's indicated that the resources appeared to be properly identified on the ESCGP mapping.

The Department reviewed and approved the ESCGP in 2017.

Page 5 of 34

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2819621	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	04/01/2019	Drilling/Alteration	003-22468	APOLLO B 1M	Yes	820926 - APOLLO B WELL PAD ESCGP ESX16-003-0009	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	FREESE, RICHARD	SUBSAIR	No Violations Noted	Patterson 343 has drilled an 8 3/4" vertical hole to a depth of 6,169'. The rig has moved to the next well. The rig will return to finish this well after drilling the other top holes.

No Violations



INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2821657	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	01/03/2019	Preoperation Inspection	003-22468	APOLLO B 1M	Yes	820926 - APOLLO B WELL PAD ESCGP ESX16-003-0009	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	STEINGRABE, SAMUEL	SAIR	No Violations Noted	Pre-Operation inspection related to a spud notification submitted on 1/2/2018. The well was planned to be stud on 1/4/2018. The PPC plan, ER plan and ESCGP mapping was on site. The Act 9 site ID sign was installed. At the time of inspection the Operator was repairing a small slough along the right side of the access road. The perimeters E&S BMPs and PCSM BMPs were installed and appeared to be functioning as designed. The disturbed areas were temporary stabilized with vegetative matting and mulch. Department recommends that the Operator continue to monitor the site weekly and after precipitation events.

No Violations

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2821661	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	01/03/2019	Preoperation Inspection	003-22467	APOLLO B 5M	Yes	820926 - APOLLO B WELL PAD ESCGP ESX16-003-0009	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	STEINGRABE, SAMUEL	SAIR	No Violations Noted	Pre-Operation inspection related to a spud notification submitted on 1/2/2018. The well was planned to be stud on 1/4/2018. The PPC plan, ER plan and ESCGP mapping was on site. The Act 9 site ID sign was installed. At the time of inspection the Operator was repairing a small slough along the right side of the access road. The perimeters E&S BMPs and PCSM BMPs were installed and appeared to be functioning as designed. The disturbed areas were temporary stabilized with vegetative matting and mulch. Department recommends that the Operator continue to monitor the site weekly and after precipitation events.

No Violations



DEP OFFICE OF OIL AND GAS MANAGEMENT  
COMPLIANCE REPORT

5/23/2019 3:26:21 PM

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2821663	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	01/03/2019	Preoperation Inspection	003-22545	APOLLO B 3M	Yes	820926 - APOLLO B WELL PAD ESCGP ESX16-003-0009	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	STEINGRABE, SAMUEL	SAIR	No Violations Noted	Pre-Operation inspection related to a spud notification submitted on 1/2/2018. The well was planned to be stud on 1/4/2018. The PPC plan, ER plan and ESCGP mapping was on site. The Act 9 site ID sign was installed. At the time of inspection the Operator was repairing a small slough along the right side of the access road. The perimeters E&S BMPs and PCSM BMPs were installed and appeared to be functioning as designed. The disturbed areas were temporary stabilized with vegetative matting and mulch. Department recommends that the Operator continue to monitor the site weekly and after precipitation events.

No Violations

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2822626	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	01/07/2019	Drilling/Alteration	003-22468	APOLLO B 1M	Yes	820926 - APOLLO B WELL PAD ESCGP ESX16-003-0009	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	FREESE, RICHARD	SUBSAIR	No Violations Noted	An auger rig has drilled a 30" hole and set 40' of 28" conductor pipe.

No Violations

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2822635	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	01/07/2019	Drilling/Alteration	003-22467	APOLLO B 5M	Yes	820926 - APOLLO B WELL PAD ESCGP ESX16-003-0009	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	FREESE, RICHARD	SUBSAIR	No Violations Noted	An auger rig has drilled a 30" hole and set 40' of 28" conductor pipe.

No Violations

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2822651	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	01/07/2019	Drilling/Alteration	003-22545	APOLLO B 3M	Yes	820926 - APOLLO B WELL PAD ESCGP ESX16-003-0009	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	FREESE, RICHARD	SUBSAIR	No Violations Noted	A track mounted auger rig is drilling a 30" hole to set 40' of 26" conductor casing.

No Violations

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2836184	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	01/28/2019	Routine/Complete Inspection	003-22545	APOLLO B 3M	Yes	820926 - APOLLO B WELL PAD ESCGP ESX16-003-0009	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	FOULK, SAMANTHA	SAIR	No Violations Noted	At the time of this inspection, well 3M has been spudded, not yet completed. Wells 1M and 5M have also been spudded, not yet completed. The rig is currently not on-site.

No Violations

DEP OFFICE OF OIL AND GAS MANAGEMENT  
COMPLIANCE REPORT

5/23/2019 3:26:21 PM

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2836186	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	01/28/2019	Routine/Complete Inspection	003-22468	APOLLO B 1M	Yes	820926 - APOLLO B WELL PAD ESCGP ESX16-003-0009	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	FOULK, SAMANTHA	SAIR	No Violations Noted	At the time of this inspection, well 1M has been spudded, not yet completed. Wells 3M and 5M have also been spudded, not yet completed. The rig is currently not on-site.

No Violations

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2836188	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	01/28/2019	Routine/Complete Inspection	003-22467	APOLLO B 5M	Yes	820926 - APOLLO B WELL PAD ESCGP ESX16-003-0009	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	FOULK, SAMANTHA	SAIR	No Violations Noted	At the time of this inspection, well 5M has been spudded, not yet completed. Wells 1M and 3M have also been spudded, not yet completed. The rig is currently not on-site.

No Violations

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2848754	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	02/27/2019	Administrative/File Review	003-22466	APOLLO B 3M	Yes	820926 - APOLLO B WELL PAD ESCGP ESX16-003-0009	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	FOULK, SAMANTHA	SAIR	In Compliance with Policy	Operator representative Scott Cleveland notified the Department via email of a 1 -2 gallon diesel fuel spill on the well pad (See Photo 1). An on-site follow-up inspection will be conducted to assess any environmental impact.

No Violations

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2848756	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	03/06/2019	Administrative/ File Review	003-22466	APOLLO B 3M	Yes	820926 - APOLLO B WELL PAD ESCGP ESX16-003-0009	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	FOULK, SAMANTHA	SAIR	In Compliance with Policy	Inspection record 2848754 was submitted in error under this well and should have been submitted under well 003-22545.

No Violations

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2848760	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	02/27/2019	Administrative/ File Review	003-22545	APOLLO B 3M	Yes	820926 - APOLLO B WELL PAD ESCGP ESX16-003-0009	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	FOULK, SAMANTHA	SAIR	In Compliance with Policy	Operator representative Scott Cleveland notified the Department via email of a 1 -2 gallon diesel fuel spill on the well pad (See Photo 1). An on-site follow-up inspection will be conducted to assess any environmental impact.

No Violations

DEP OFFICE OF OIL AND GAS MANAGEMENT  
COMPLIANCE REPORT

5/23/2019 3:26:21 PM

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2849022	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	02/28/2019	Routine/Complete Inspection	003-22467	APOLLO B 5M	Yes	820926 - APOLLO B WELL PAD ESCGP ESX16-003-0009	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	FOULK, SAMANTHA	SAIR	No Violations Noted	At the time of this inspection, well 5M has been spudded, not yet completed. Wells 1M and 3M have also been spudded, not yet completed. The rig is currently not on-site.

No Violations

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2849027	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	02/28/2019	Routine/Complete Inspection	003-22468	APOLLO B 1M	Yes	820926 - APOLLO B WELL PAD ESCGP ESX16-003-0009	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	FOULK, SAMANTHA	SAIR	No Violations Noted	At the time of this inspection, well 1M has been spudded, not yet completed. Wells 3M and 5M have also been spudded, not yet completed. The rig is currently not on-site.

No Violations

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2849032	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	02/28/2019	Routine/Complete Inspection	003-22545	APOLLO B 3M	Yes	820926 - APOLLO B WELL PAD ESCGP ESX16-003-0009	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	FOULK, SAMANTHA	SAIR	No Violations Noted	At the time of this inspection, well 3M has been spudded, not yet completed. Wells 1M and 5M have also been spudded, not yet completed. The rig is currently not on-site.

No Violations

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2855127	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	03/11/2019	Routine/Partial Inspection	003-22467	APOLLO B 5M	Yes	820926 - APOLLO B WELL PAD ESCGP ESX16-003-0009	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	FOULK, SAMANTHA	SAIR	No Violations Noted	At the time of this inspection, well 5M has been spudded, not yet completed. Wells 1M and 3M have also been spudded, not yet completed. The rig is currently not on-site.

No Violations

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2855129	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	03/11/2019	Routine/Partial Inspection	003-22468	APOLLO B 1M	Yes	820926 - APOLLO B WELL PAD ESCGP ESX16-003-0009	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	FOULK, SAMANTHA	SAIR	No Violations Noted	At the time of this inspection, well 1M has been spudded, not yet completed. Wells 3M and 5M have also been spudded, not yet completed. The rig is currently not on-site.

No Violations



DEP OFFICE OF OIL AND GAS MANAGEMENT  
COMPLIANCE REPORT

5/23/2019 3:26:21 PM

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2855131	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	03/11/2019	Routine/Partial Inspection	003-22545	APOLLO B 3M	Yes	820926 - APOLLO B WELL PAD ESCGP ESX16-003-0009	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	FOULK, SAMANTHA	SAIR	No Violations Noted	At the time of this inspection, well 3M has been spudded, not yet completed. Wells 1M and 5M have also been spudded, not yet completed. The rig is currently not on-site.

No Violations

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2861002	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	04/01/2019	Drilling/Alteration	003-22467	APOLLO B 5M	Yes	820926 - APOLLO B WELL PAD ESCGP ESX16-003-0009	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	FREESE, RICHARD	SUBSAIR	No Violations Noted	Patterson 343 has just moved over this well and has not yet started drilling.

No Violations

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2861846	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	04/02/2019	Drilling/Alteration	003-22467	APOLLO B 5M	Yes	820926 - APOLLO B WELL PAD ESCGP ESX16-003-0009	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	FREESE, RICHARD	SUBSAIR	No Violations Noted	Patterson rig is running 326' of coal protective casing. A basket will be set at 259'.

No Violations

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2867520	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	04/13/2019	Administrative/ File Review	003-22545	APOLLO B 3M	Yes	820926 - APOLLO B WELL PAD ESCGP ESX16-003-0009	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	FOULK, SAMANTHA	SAIR	In Compliance with Policy	<div>SPILL.</div> <div>ON 4/13/19 AT 0809, OPERATOR REPRESENTATIVE SCOTT CLEVELAND NOTIFIED THE AFTER-HOURS TAS OF A RELEASE OF WATER/SOAP/DRILL CUTTINGS ONTO THE PAD. 95% REPORTED TO BE ON THE PAD AND 5% REPORTED TO BE ON GROUND.</div> <div>IT IS REPORTED TO BE CONTAINED AND BEING CLEANED UP.</div> <div>IT IS REPORTED TO HAVE OCCURRED AT 0430.</div> <div>This admin inspection documents the reporting of this release. Violations may be forthcoming upon review and investigation.</div>

No Violations

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2867523	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	04/15/2019	Administrative/ File Review	003-22545	APOLLO B 3M	Yes	820926 - APOLLO B WELL PAD ESCGP ESX16-003-0009	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	FOULK, SAMANTHA	SAIR	In Compliance with Policy	<p>Admin inspection. Operator representative Scott Cleveland provided an email to the Department on 4/13/19 at 1109 in response to a release reported under inspection record 2867520.</p> <p>Per Mr. Cleveland: "This morning at approximately 430am while drilling on air on the Apollo B 3M well, a flow line separated and a mixture of water, drill cuttings and soap were released to the pad surface and onto the sound wall on the western side of the Apollo B pad. Additionally, a light mist of this mixture was deposited over a portion of the berm and western slope of the pad. I arrived on site at approximately 645am and surveyed the situation. I called the 24 hour DEP hotline at 8:08am and notified them of the release. We are still trying to determine an accurate quantity at this time and will update the department as soon as possible. Cleanup has begun to remove the material from the pad and berm area."</p> <p>Violations may be forthcoming upon further review and investigation.</p>

No Violations

#fileroom  
OPEN-SOURCE V.1.1

DEP OFFICE OF OIL AND GAS MANAGEMENT  
COMPLIANCE REPORT

5/23/2019 3:26:21 PM

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2867525	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	04/15/2019	Administrative/ File Review	003-22545	APOLLO B 3M	Yes	820926 - APOLLO B WELL PAD ESCGP ESX16-003-0009	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	FOULK, SAMANTHA	SAIR	In Compliance with Policy	<p>Admin inspection. Operator representative Scott Cleveland provided an email to the Department on 4/14/19 at 1155 in response to a release reported under inspection record 2867520.</p> <p>Mr. Cleveland provided an update to the email previously provided to the Department under inspection record 2867523.</p> <p>Per Mr. Cleveland: "After evaluation of the flow rate and duration of the release described below, HHEX estimates that no more than 5 barrels of the material was released and was deposited both on and off containment. Cleanup of the material was conducted yesterday. There were no waterways threatened or impacted due to this release."</p> <p>Violations may be forthcoming upon further review and investigation.</p>

No Violations

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2867552	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	04/15/2019	Administrative/ File Review	003-22545	APOLLO B 3M	Yes	820926 - APOLLO B WELL PAD ESCGP ESX16-003-	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	FOULK, SAMANTHA	SAIR	Violation(s) Noted	Admin inspection in response to a release

0009

reported to the Department under inspection record 2867520. Email updates were provided to the Department by the operator under inspection records 2867523 and 2867525.

In response to the spill notification, the Department contacted operator representative Scott Cleveland by phone. Per the Department's conversation with Mr. Cleveland: A release of no more than 5 bbl of water, soap, and drill cuttings occurred when a pipe separated, subsequently spraying the sound wall. As a result, the released fluids remained on the pad. Some fluids landed on the western portion of the pad's berm when the spray misted and was carried by the wind. The containment and sound wall has been cleaned. The matting on the berm was removed and replaced yesterday 4/14. The release occurred while drilling with air on the 3M well; drilling was at an approximate depth of 400 feet. The quantity released off of containment is unknown, but it was more than 1 bbl. Mr. Cleveland does not believe that the released fluids reached any pad drains; the pad drains are





# DEP OFFICE OF OIL AND GAS MANAGEMENT COMPLIANCE REPORT

currently closed, but will be checked prior to opening these drains. The operator intends to remediate this release in accordance with Act 2 standards per 78a.66(c)2. The Department requested the SDSs for any materials released; Mr. Cleveland agreed to provide these to the Department.

As discussed with Mr. Cleveland, in accordance with 78a.66(c)2i, an initial written report shall be provided to the Department within 15 business days of the spill or release. In this initial report and/or summary, please identify all constituents of concern that will be analyzed.

Violations are being issued for the operator's failure to report a release of more than 5 gallons of a regulated substance in accordance with 78a.66(b)2.

A follow-up on-site inspection will be conducted to assess any environmental impact and/or issue any associated violations as necessary.

Page 21 of 34

VIOLATION ID	VIOLATION DATE	VIOLATION CODE & DESCRIPTION	VIOLATION TYPE	VIOLATION COMMENT	RESOLVED DATE	RESOLUTION REASON CODE & DESCRIPTION	CONTINUING VIOLATION	RELATED ENFORCEMENTS
846664	04/15/2019	78a66(b)2 - REPORTING AND REMEDIATING SPILLS AND RELEASES – Reporting releases - Operator or other responsible party failed to contact the appropriate regional Department office by telephone or call the Department’s Statewide toll free number as soon as practicable, but no later than 2 hours after discovering the spill or release.	Environmental Health & Safety	A violation is being issued and noted as immediately corrected for the operator's failure to report a release of more than 5 gallons within 2 hours of discovering the release.	04/15/2019	CRCTD - Corrected/Abated		373822

Enforcement Details

ENFORCEMENT ID	ENFORCEMENT CODE & DESCRIPTION	EXECUTED ENFORCEMENT DATE	ENFORCEMENT FINAL DATE	ENFORCEMENT FINAL STATUS	PENALTY FINAL DATE	PENALTY FINAL STATUS CODE & DESCRIPTION	PENALTY AMOUNT	TOTAL AMOUNT COLLECTED	RELATED VIOLATIONS
373822	NOV - Notice of Violation	04/15/2019							846664

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2867901	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	04/16/2019	Drilling/Alterati on	003-22545	APOLLO B 3M	Yes	820926 - APOLLO B WELL PAD ESCGP ESX16-003-0009	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	FREESE, RICHARD	SUBSAIR	No Violations Noted	Patterson 343 is drilling top hole with air. The 9 5/8" casing is in and set at 2,507'. At this time they are cleaning the hole before cementing.

No Violations

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2870626	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	04/15/2019	Administrative/ File Review	003-22545	APOLLO B 3M	Yes	820926 - APOLLO B WELL PAD ESCGP ESX16-003-0009	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	FOULK, SAMANTHA	SAIR	In Compliance with Policy	<div>Admin inspection in response to a release reported to the Department under inspection record 2867520.</div> <div>Operator representative Scott Cleveland electronically provided the SDS for the soap (Mega Mist HD) released as previously requested by the Department in inspection record 2867552.</div> <div>A follow-up on-site inspection will be conducted to assess any environmental impact and/or issue any associated violations as necessary.</div>

No Violations

DEP OFFICE OF OIL AND GAS MANAGEMENT  
COMPLIANCE REPORT

5/23/2019 3:26:21 PM

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2870630	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	04/16/2019	Administrative/ File Review	003-22545	APOLLO B 3M	Yes	820926 - APOLLO B WELL PAD ESCGP ESX16-003-0009	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	FOULK, SAMANTHA	SAIR	In Compliance with Policy	<p>Admin inspection in response to a release reported to the Department under inspection record 2867520.</p> <p>Operator representative Scott Cleveland provided an email to the Department on the status of the release remediation (See attached).</p> <p>A follow-up on-site inspection will be conducted to assess any environmental impact and/or issue any associated violations as necessary.</p>

No Violations

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2870718	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	04/17/2019	Incident- Response to Accident or Event	003-22545	APOLLO B 3M	Yes	820926 - APOLLO B WELL PAD ESCGP ESX16-003-0009	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	FOULK, SAMANTHA	SAIR	Violation(s) Noted	<p>On-site incident inspection in response to a release reported to the Department under inspection record 2867520.</p> <p>Inspection conducted with Environmental Trainee Eric Norman.</p> <p>Accompanied by Operator representatives Scott Cleveland, Laura Karosic, and Kyle Shirey.</p> <p>At the time of this inspection, drilling operations are actively</p>

ongoing for well 3M. Wells 1M and 5M have been drilled to the KOP.

Mr. Cleveland showed the Department where the release originated as a result of a pipe disconnecting near the rig, where the released fluids hit the sound wall, and where a mist of this fluid was carried over the wall. A release of 5 bbl water, drill cuttings, and soap (Mega Mist HD) is estimated to have occurred. At this time, the vegetative matting on the western berm of the well pad outside of the sound wall has been replaced (Photos #1 and #2); the removed contaminated matting is currently wrapped in tarp at the base of this berm (Photo #1).

There is rock on the edge of the pad, with a drain system underneath, between this berm and the sound wall (Photo #2). Mr. Cleveland reports only a very small amount of the released fluids got on this rock and the drains are currently closed; the drains will be checked for any released fluids prior to opening should any fluids have traveled within.

Mr. Cleveland showed the Department the inside of the sound wall that was sprayed and the secondary



**DEP OFFICE OF OIL AND GAS MANAGEMENT  
COMPLIANCE REPORT**

containment that caught fluids (Photo #3). Between this secondary containment and sound wall is a thin strip of well pad (Photo #4). The sound wall and secondary containment, including the contents on the containment, were power-washed after the release.

The operator hired a third party to remediate the release in accordance with Act 2 standards and this consultant is anticipated to be on-site tomorrow to begin this process.

Violations are being issued for this reportable release of fluids.

## Violation Details



VIOLATION ID	VIOLATION DATE	VIOLATION CODE & DESCRIPTION	VIOLATION TYPE	VIOLATION COMMENT	RESOLVED DATE	RESOLUTION REASON CODE & DESCRIPTION	CONTINUING VIOLATION	RELATED ENFORCEMENTS
847430	04/17/2019	91.34(A) - ACTIVITIES UTILIZING POLLUTANTS - Failure to take necessary measures to prevent the substances from directly or indirectly reaching waters of this Commonwealth, through accident, carelessness, maliciousness, hazards of weather or from another cause.	Environmental Health & Safety	A violation is being issued for failure to comply with 91.34(a). Specifically, a 5 bbl release of water/drill cuttings/Mega Mist HD occurred off of secondary containment.				373822
847431	04/17/2019	78a54 - GENERAL REQUIREMENTS - Operator failed to control and dispose of fluids, residual waste and drill cuttings, including tophole water, brines, drilling fluids, drilling muds, stimulation fluids, well servicing fluids, oil, and production fluids in a manner that prevents pollution of the waters of the Commonwealth and in accordance with 25 Pa. Code §§ 78a.55 – 78a.58 and 78a.60 – 78a.63.	Environmental Health & Safety	A violation is being issued for failure to comply with 78a54. Specifically, a 5 bbl release of water/drill cuttings/Mega Mist HD occurred off of secondary containment.				373822
847432	04/17/2019	SWMA 301 - MANAGEMENT OF RESIDUAL WASTE - Person operated a residual waste processing or disposal facility without obtaining a permit for such facility from DEP. Person stored, transported, processed, or disposed of residual waste inconsistent with or unauthorized by the rules and regulations of DEP.	Environmental Health & Safety	A violation is being issued for failure to comply with SWMA 301. Specifically, a 5 bbl release of water/drill cuttings/Mega Mist HD occurred off of secondary containment.				373822
847433	04/17/2019	78a64a(b) - SECONDARY CONTAINMENT – All regulated substances, including solid wastes and other regulated substances in equipment or vehicles, failed to be managed within secondary containment on the well site.	Environmental Health & Safety	A violation is being issued for failure to comply with 78a64a(b). Specifically, a 5 bbl release of water/drill cuttings/Mega Mist HD occurred off of secondary containment.				373822

Enforcement Details

ENFORCEMENT ID	ENFORCEMENT CODE & DESCRIPTION	EXECUTED ENFORCEMENT DATE	ENFORCEMENT FINAL DATE	ENFORCEMENT FINAL STATUS	PENALTY FINAL DATE	PENALTY FINAL STATUS CODE & DESCRIPTION	PENALTY AMOUNT	TOTAL AMOUNT COLLECTED	RELATED VIOLATIONS
373822	NOV - Notice of Violation	04/15/2019							847433
									847432
									847431
									847430

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2870727	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	04/17/2019	Routine/Partial Inspection	003-22468	APOLLO B 1M	Yes	820926 - APOLLO B WELL PAD ESCGP ESX16-003-0009	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	FOULK, SAMANTHA	SAIR	No Violations Noted	<p>On-site incident inspection in response to a release reported to the Department under inspection record 2867520. Violations for this release were issued under inspection record 2870718 against well 3M.</p> <p>Inspection conducted with Environmental Trainee Eric Norman. Accompanied by Operator representatives Scott Cleveland, Laura Karosic, and Kyle Shirey.</p> <p>At the time of this inspection, well 1M has been drilled to the KOP. Well 5M has also been drilled to the KOP. Currently, drilling operations are actively ongoing for well 3M.</p> <p>Site ID sign installed at access road entrance. Site-specific ERP on-site. Site-specific PPC plan on-site. Tanks are labeled with the contents and corresponding warnings.</p>

No Violations

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2870729	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	04/17/2019	Routine/Partial Inspection	003-22467	APOLLO B 5M	Yes	820926 - APOLLO B WELL PAD ESCGP ESX16-003-0009	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	FOULK, SAMANTHA	SAIR	No Violations Noted	<p>On-site incident inspection in response to a release reported to the Department under inspection record 2867520. Violations for this release were issued under inspection record 2870718 against well 3M.</p> <p>Inspection conducted with Environmental Trainee Eric Norman. Accompanied by Operator representatives Scott Cleveland, Laura Karosic, and Kyle Shirey.</p> <p>At the time of this inspection, well 5M has been drilled to the KOP. Well 1M has also been drilled to the KOP. Currently, drilling operations are actively ongoing for well 3M.</p> <p>Site ID sign installed at access road entrance. Site-specific ERP on-site. Site-specific PPC plan on-site. Tanks are labeled with the contents and corresponding warnings.</p>

No Violations

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2877123	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	05/08/2019	Drilling/Alteration	003-22539	PLUTUS 7M	Yes	827093 - PLUTUS WELL PAD & CETO TANK PAD ESCGP ESX17-003-0010	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	FREESE, RICHARD	SUBSAIR	No Violations Noted	NOV auger rig is drilling a 36" hole to install a 26" conductor. The conductor casing will be set at 42' and cemented to the bottom of the cellar:

No Violations

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2877125	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	05/08/2019	Drilling/Alteration	003-22537	PLUTUS 5M	Yes	827093 - PLUTUS WELL PAD & CETO TANK PAD ESCGP ESX17-003-0010	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	FREESE, RICHARD	SUBSAIR	No Violations Noted	NOV auger rig is drilling a 36" hole to install a 26" conductor. The conductor casing will be set at 42' and cemented to the bottom of the cellar:

No Violations

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2877131	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	05/08/2019	Drilling/Alteration	003-22535	PLUTUS 3M	Yes	827093 - PLUTUS WELL PAD & CETO TANK PAD ESCGP ESX17-003-0010	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	FREESE, RICHARD	SUBSAIR	No Violations Noted	NOV auger rig is drilling a 36" hole to install a 26" conductor. The conductor casing will be set at 42' and cemented to the bottom of the cellar:

No Violations

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2878194	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	04/29/2019	Administrative/ File Review	003-22545	APOLLO B 3M	Yes	820926 - APOLLO B WELL PAD ESCGP ESX16-003-0009	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	FOULK, SAMANTHA	SAIR	In Compliance with Schedule	<p>On-site incident inspection in response to a release reported to the Department under inspection record 2867520. Violations for this release were issued under inspection record 2870718.</p> <p>Operator representative Laura Karosic provided the written report for this release in accordance with regulations to the Department via email.</p> <p>As the operator has provided a schedule for remediation, the violations are being closed at this time. Additional violations may be forthcoming upon further inspections monitoring the remediation of this release.</p> <p>The Department is requesting the operator provide a list of constituents of concern that are being analyzed for this release.</p>

No Violations

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2878753	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	05/02/2019	Administrative/ File Review	003-22545	APOLLO B 3M	Yes	820926 - APOLLO B WELL PAD ESCGP ESX16-003-0009	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	FOULK, SAMANTHA	SAIR	In Compliance with Policy	Inspection record 2878194 was erroneously identified as an on-site incident inspection. For clarification, inspection record 2878194 was an admin Compliance Evaluation Inspection in response to violations issued under inspection record 2870718 for a reportable release reported to the Department under inspection record 2867520.

No Violations

INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2878755	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	05/03/2019	Administrative/ File Review	003-22545	APOLLO B 3M	Yes	820926 - APOLLO B WELL PAD ESCGP ESX16-003-0009	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	FOULK, SAMANTHA	SAIR	In Compliance with Policy	Admin inspection in response to a release reported to the Department under inspection record 2867520. Violations for this release were issued under inspection record 2870718 and closed as ICS under inspection record 2878194.  Operator representative Laura Karosic provided the requested written NOV response to the Department via email.

No Violations



INSPECTION ID	INSPECTION CLIENT NAME	INSPECTION DATE	INSPECTION TYPE	API / PERMIT	FARM NAME	UNCONVENTIONAL	SITE ID / NAME	FACILITY TYPE	INSPECTION CATEGORY	REGION	COUNTY	MUNICIPALITY	INSPECTOR	INSPECTION SOURCE	INSPECTION RESULT DESCRIPTION	INSPECTION COMMENT
2878757	HUNTLEY & HUNTLEY ENERGY EXPLORATION LLC	05/03/2019	Administrative/ File Review	003-22545	APOLLO B 3M	Yes	820926 - APOLLO B WELL PAD ESCGP ESX16-003-0009	Oil & Gas Location	Primary Facility	EP DOGO SWDO Dstr Off	Allegheny	Elizabeth Twp	FOULK, SAMANTHA	SAIR	In Compliance with Policy	<div>Admin inspection in response to violations issued and noted as immediately corrected under inspection record 2867552.</div> <div>Operator representative Laura Karosic provided the requested written NOV to the Department via email.</div>

No Violations



**Grand Total -    Inspections: 53; Inspections With Violations: 2; Violations: 5; Enforcements: 1; Wells Inspected: 12**